

Billion 7402V Series.

Firmware v5.04a dk5 Release Notes.

This document and the included firmware are Copyright © 2005 Billion Electric Co.,

PC Range Pty Ltd. All Rights Reserved. No part of this document may be posted publicly without the express written consent of PC Range Pty Ltd. The included firmware release is intended for use in Australia only. Unauthorised distribution of Billion firmware or this document is strictly prohibited. For releases outside Australia please refer to the Billion Taiwan website at www.billion.com or contact them via email support@billion.com

Australian users should only use firmware downloaded from the official Billion Australia website at www.billion.com.au or supplied by Billion Australia and PC Range agents and staff. All Billion products and firmware are provided “as is” and no responsibility is taken for any loss or damage that may result from their use. The use of Beta firmware may increase the risk of instability or other issues with your router.

All users should reset the router to factory-default settings after upgrading firmware.

7402VGO users must reset their router to factory-default settings before attempting to upgrade firmware.

(This is should not be necessary for users of other 7402V models.)

Version: 5.04k dk5 (20th September 2005):

- Fixed two memory leak issues in VoIP-related functions.
- Added VoIP volume control to web interface, and ability to save values to flash.
- Fixed iiNetPhone PRACK issue.
- Fixed iiNetPhone expire time issue.
- Fixed LINE LED issue.
- Fixed Australian Caller ID generation issue.