

Release note

8700AXL

FW version: 2.52.d7

New Features / Functions

1. Supported software restart on dongle-E5573/E8372/MF910
2. Added logout button.

Modifications & Bug Fixes:

1. Fix a vulnerability in the device driver
2. Fixed 5G MAC filter issue
3. Fixed bridge mode on Netgear AirCard 810S
4. Fixed URL filter issue