

Release note

8700AXL

FW version: 2.52.d6

New Features / Functions

N/A

Modifications & Bug Fixes:

1. Fixed warm boot/hardware boot issue on E3372h.
2. Modify default customization
3. Fixed LAN port 5 need reboot manually to active after remove EWAN interface.
4. Fixed AirCard790S detection after power off/on.
5. Fixed DDNS- zoneedit issue
6. Fixed No-IP display issue.
7. Fixed BT issue to cause Router reboot.