

## Release note

### 8207AX

FW version: 3.44.r4

#### **New Features / Functions:**

1. Added ALG in Service > Firewall > ALG
2. Supported all IP addresses within and without the DHCP Range in LAN > DHCP > MAC-Based Assignment
3. Improved Samba Account in Management > Samba Account
4. Increased Port Forwarding rules to 64

#### **Modifications & Bug Fixes:**

1. Fixed issue with Shrew VPN passthrough
2. Fixed issue with no traffic after establishing L3 Failover  
(Case 1: Master/PTM and Slave/LTE; Case 2: Master/EWAN, PPPoE and Slave/LTE)
3. Set the default IPV6 Address Mode in the PTM interface to Auto Detection Mode. When upgrading to this new firmware, please select the default configuration.

**✓ Notice:**

The IPV6 feature has been turn off by default; please enable it from Advance > IPV6 >IPV6.