

Release note

8207AZ

FW version: 3.44.r6

New Features / Functions:

1. Added Bridge Mode in 3G/4G Settings Page
2. Added ALG in Service > Firewall > ALG
3. Supported all IP addresses within and without the DHCP Range in LAN > DHCP > MAC-Based Assignment
4. Improved Samba Account in Management > Samba Account
5. Increased Port Forwarding rules to 64

Modifications & Bug Fixes:

1. Fixed issue with Shrew VPN passthrough
2. Fixed issue with no traffic after establishing L3 Failover
(Case 1: Master/PTM and Slave/LTE; Case 2: Master/EWAN, PPPoE and Slave/LTE)
3. Set the default IPV6 Address Mode in the PTM interface to Auto Detection Mode. When upgrading to this new firmware, please select the default configuration.

✓ Notice:

The IPV6 feature has been turn off by default; please enable it from Advance > IPV6 >IPV6.