

Release note

8700AXL

FW version: 2.52.d13

Modifications & Bug Fixes:

1. Factory default settings changed in DSL, WiFi, and LAN DHCP Server.

✓ Notice:

By default, "IPV6" and "Issue Router Advertisements" features have been disabled.
Please enable them at Configuration > LAN > IPV6 Autoconfig for IPV6 connection.