

Release note

8900AX-2400

FW version: 2.52.d44

Modifications & Bug Fixes:

1. Fixed drop button issue from server UI and no traffic pass-through when using account 6~8 via L2TP over IPSEC.
2. Factory default settings changed in DSL, WiFi, and LAN DHCP Server.

✓ Notice:

It is recommended to choose factory default when upgrading the FW from 2.50a.xxx to 2.52.xxx.

By default, "IPV6" and "Issue Router Advertisements" features have been disabled. Please enable them at Configuration > LAN > IPV6 Autoconfig for IPV6 connection.