

## Release note

### 8900X R3

FW version: 2.52.d14

#### Modifications & Bug Fixes:

1. Fixed 3G/4G LTE default route issue after reboot.

**✓ Notice:**

It is recommended to choose factory default when upgrading the FW from 2.50a.xxx to 2.52.xxx.

By default, "IPV6" and "Issue Router Advertisements" features have been disabled.

Please enable them at Configuration > LAN > IPV6 Autoconfig for IPV6 connection.