

Release note

8700VAX

FW version: 2.52.d16

Modifications & Bug Fixes:

1. Added new OpenVPN HMAC Authentication for more security support for SHA256, SHA384, SHA512.
2. Change HTTP Session timeout to 10 minutes.
3. Fixed config error in <Configure log page> issue

✓ Notice:

By default, "IPV6" and "Issue Router Advertisements" features have been disabled.
Please enable them at Configuration > LAN > IPV6 Autoconfig for IPV6 connection.