

Release note

8700VAXL

FW version: 2.52.d14

Modifications & Bug Fixes:

1. Factory default settings changed in DSL, WiFi, and LAN DHCP Server.
2. IPv6 enhancement on EWAN-IPoE connection.
3. Improve 2.4G and 5G WLAN connectivity when setting up QoS.
4. Support multiple WAN IPs in the same interface on Virtual Serve.

✓ Notice:

By default, "IPV6" and "Issue Router Advertisements" features have been disabled.
Please enable them at Configuration > LAN > IPV6 Autoconfig for IPV6 connection.