

Release note

8900AX-2400

FW version: 2.52.d51

Modifications & Bug Fixes:

1. Users can now generate random CA on OpenVPN server.
2. Added new OpenVPN HMAC Authentication for more security support for SHA256, SHA384, SHA512.
3. Change HTTP Session timeout to 10 minutes.
4. Fixed config error in <Configure log page> issue
5. Fixed 3G/4G LTE default route issue after reboot

✓ Notice:

It is recommended to choose factory default when upgrading the FW from 2.50a.xxx to 2.52.xxx.

By default, "IPV6" and "Issue Router Advertisements" features have been disabled. Please enable them at Configuration > LAN > IPV6 Autoconfig for IPV6 connection.